

MARYLAND HISTORICAL TRUST
21 STATE CIRCLE
SHAW HOUSE
ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
Individual Structure Survey Form

SURVEY NUMBER: AA 456

NEGATIVE FILE NUMBER:

UTM REFERENCES:
Zone/Easting/Northing

U.S.G.S. QUAD. MAP:

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Commercial

ORIGINAL USE: Commercial

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent ()

Good ()

Fair (x)

Poor: ()

THEME:

STYLE: None

DATE BUILT:

1891-1897 Altered

COUNTY: Anne Arundel

TOWN: Annapolis

LOCATION:

118 Dock St.

COMMON NAME:

FUNCTIONAL TYPE: COMM Map 33 Par 79

OWNER: (119 Prince George)

ADDRESS: Campbell Robert H & Annie J
121 Prince George, Annapolis, MD

ACCESSIBILITY TO PUBLIC:

Yes (x) No () Restricted ()

LEVEL OF SIGNIFICANCE:

Local () State () National ()

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone () Brick (x) Concrete () Concrete Block ()
2. Wall Structure
 - A. Wood Frame: Post and Beam () Balloon ()
 - B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - C. Iron () D. Steel () E. Other: Arch. Tile
3. Wall Covering: Clapboard () Board and Batten () Wood Shingle () Shiplap ()
Novelty () Stucco (x) Sheet Metal () Aluminum () Asphalt Shingle ()
Brick Veneer (x) Stone Veneer () Asbestos Shingle ()
Bonding Pattern: Common Other:
4. Roof Structure
 - A. Truss: Wood (x) Iron () Steel () Concrete ()
 - B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal ()
Built Up (x) Rolled () Tile () Other:
6. Engineering Structure:
7. Other:

Appendages: Porches () Towers () Cupolas () Dormers () Chimneys () Sheds () Ells ()
Wings () Other:

Roof Style: Gable () Hip () Shed () Flat (x) Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
Other:

Number of Stories: 2

Number of Bays: 2

Approximate Dimensions: 20 x 35

Entrance Location: Centered

THREAT TO STRUCTURE:

No Threat (x) Zoning () Roads ()
Development () Deterioration ()
Alteration () Other:

LOCAL ATTITUDES:

Positive () Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-456


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

No architectural significance.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane() Woodland() Scattered Buildings()
Moderately Built Up() Densely Built Up(✓)
Residential() Commercial()
Agricultural() Industrial()
Roadside Strip Development()
Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug - 1983

MARYLAND HISTORICAL TRUST
21 STATE CIRCLE
SHAW HOUSE
ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
Individual Structure Survey Form

SURVEY NUMBER:

AA 456

NEGATIVE FILE NUMBER:

UTM REFERENCES:

Zone/Easting/Northing

U.S.G.S. QUAD. MAP:

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Retail/Apt.

ORIGINAL USE: Retail/ Apt.

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent()

Good()

Fair(x)

Poor: ()

THEME:

STYLE: Victorian Commercial

DATE BUILT:

c 1880 Altered

COUNTY: Anne Arundel

TOWN: Annapolis

LOCATION:

120 Dock St.

COMMON NAME:

FUNCTIONAL TYPE: COMM Map 33Par 72

OWNER: Campbell Robt H

ADDRESS: 121 Prince George St.

Annapolis, MD 21401

ACCESSIBILITY TO PUBLIC:

Yes(x) No () Restricted()

LEVEL OF SIGNIFICANCE:

Local(✓) State () National()

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone() Brick(x) Concrete() Concrete Block()
2. Wall Structure
 - A. Wood Frame: Post and Beam() Balloon(x)
 - B. Wood Bearing Masonry: Brick() Stone() Concrete() Concrete Block()
 - C. Iron() D. Steel() E. Other:
3. Wall Covering: Clapboard() Board and Batten() Wood Shingle() Shiplap()
Novelty() Stucco(x) Sheet Metal() Aluminum() Asphalt Shingle()
Brick Veneer() Stone Veneer() Asbestos Shingle()
Bonding Pattern: Other:
4. Roof Structure
 - A. Truss: Wood(x) Iron() Steel() Concrete()
 - B. Other:
5. Roof Covering: Slate() Wood Shingle() Asphalt Shingle() Sheet Metal()
Built Up() Rolled(x) Tile() Other:
6. Engineering Structure:
7. Other:

Appendages: Porches() Towers() Cupolas() Dormers() Chimneys() Sheds() Ells()
Wings() Other:

Roof Style: Gable() Hip() Shed(x) Flat() Mansard() Gambrel() Jerkinhead()
Saw Tooth() With Monitor() With Bellcast() With Parapet() With False Front()
Other:

Number of Stories: 2

Number of Bays: 3

Approximate Dimensions: 20 x 60

Entrance Location: Centered

THREAT TO STRUCTURE:

No Threat(x) Zoning() Roads()
Development() Deterioration()
Alteration() Other:

LOCAL ATTITUDES:

Positive() Negative()
Mixed() Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-456

Bracketed cornice with deep frieze, altered shopfront.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Moderate example of Italianate commercial with poor first floor; in scale with streetfront.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane() Woodland() Scattered Buildings()
Moderately Built Up(✓) Densely Built Up()
Residential() Commercial()
Agricultural() Industrial()
Roadside Strip Development()
Other:

RECORDED BY:

Russell Wright

ORGANIZATION:


Historic Annapolis, Inc

DATE RECORDED:


Aug. 1983

0204561611

Form 10-445
(5/62)


1. STATE Annapolis, Maryland COUNTY TOWN STREET NO. 118 - 122 Dock Street VICINITY ORIGINAL OWNER ORIGINAL USE commercial PRESENT OWNER PRESENT USE Sadler's Hardware WALL CONSTRUCTION brick NO. OF STORIES three		HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY 2. NAME Sadler's DATE OR PERIOD 1880s - 1890s STYLE Victorian commercial ARCHITECT BUILDER 3. FOR LIBRARY OF CONGRESS USE	
4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION Sadler's Hardware occupies an example of late Victorian commercial architecture. It is one of those many buildings in Annapolis that has sides not at 90° from the facade. The storefront has been "colonialized" and has a metal hood-roof above it. The 2nd storey has 6 unevenly spaced 1/2/1 windows with splayed brick lintels and brick keystones. The 3rd storey is a shingle mansard roof with 4 very decorative dormers. The shingles are laid up in a fish scale pattern (see Nos. 97, 99 Cathedral St.) The mansard and dormers are hidden by a large sign which should be removed. Both Sadler's and Stevens are same scale and form a nice frame for Nos. 132 and 136.		OPEN TO PUBLIC yes	
			
5. PHYSICAL CONDITION OF STRUCTURE		Endangered Interior Exterior good	
6. LOCATION MAP (Plan Optional)		7. PHOTOGRAPH	
8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC. Constance Werner Historic Annapolis, Inc.		9. NAME, ADDRESS AND TITLE OF RECORDER William D. Morgan Columbia University New York City DATE OF RECORD July 18, 1967	

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



AA 456
ANNAPOILIS HIST. DIST.

0 50 100 200 300 400 500 SCALE IN FEET





AA-456

PHOTOGRAPH BY
WILLIAM D. MORGAN

118-132 Dock 8T
III / 18 / 67



120 Dock

AA 456

Annapolis, Anne Arundel County

Russell Wright July, 1980

Maryland Historical Trust,

Annapolis, Maryland

SW Elevation/camera facing NE